10

ABSTRACT

First and second metal members W1, W2 are joined by lapping at least two metal members one over the other; pressing a rotating tool 1 against the outmost surface of the lapped metal members, that is, the first metal member W1; and stirring the metal structure between the first and second metal members W1, W2 by the use of frictional heat generated by the rotating motion of the rotating tool 1 while keeping the metal members in a non-molten state.